« I-PASS Mounting for Vehicles with Special Windshield Features »

The vehicles listed below have been identified by the Illinois Tollway as having special features that require an exterior License Plate Tag (LPT) or alternative placement as noted. In general, windshields that contain metal in the glass (metal oxide) and mirrors with compass or temperature readings may prevent the I-PASS signal from being read properly. Also, the following glass features may interfere with the I-PASS signal and require alternative or exterior mounting: solar ray, solar tint, heated, heat reflected, insulated, Insta-Clear. Please contact the dealership where you purchased your car to see if your vehicle contains any of these features.

Make	Model	Year(s)	Feature	Alternative Placement
<u>Audi</u>				
	A-4			
	A-6	97-99	Insulated Glass	
	A-8	97-99	Insulated Glass/Heated	
	All Models	95-98	Heated	
BMW				
	750-700 LI	00-07	Metallized Windshield	All Models: Centered below rearview
	500 Series	99-00		mirror. Half of the transponder should be
	700 Series	99-00		in the tinting and the other half out
Buick				
	All Models	99	Solar Ray	
	Century	96-02	Heat Reflective	
	Park Ave	91-99 / 01-02	Solar Ray	
	Regal	96-98 / 01-02	Heat Reflective	
	Riviera	92-99	Solar Control	
	Roadmaster	All	Solar Ray	
	Rendezvous	00-07		Top right corner of windshield
<u>Cadillac</u>				
	Catera	99-01	Solar Ray	
	Concours	92-95 / 99-01	Heated/Solar Ray	
	Coupe DeVille	92-07	Heated	
	DeVille	92-07	Heated/Solar Ray	
	Eldorado	95/99-02	Solar Ray	
	Escalade	99-00 / 02	Solar Ray	
	Fleetwood	90-96	SunGate/Heated/Metal Oxide	
	Fleetwood Brougham		Metal Oxide	
	Seville STS	92-96 / 99-02 92/95/06	Heated Metal Windshield	Pottom right corner of windshield
	Touring Sedan	92/95/06	Heated	Bottom right corner of windshield
	60 Special	92-94	Heated	
	oo special	JZ-30	ricated	I·PASS

Make	Model	Year(s)	Feature	Alternative Placement
Chevrole	t			
	All Models	99	Solar Ray / Solar Control	
	Caprice	92-98	Heat Reflective	
	Cavalier	99 / 01-02	Solar Band	
	Celebrity	97-98	Metal Oxide	
	Corvette	97-98	Heat Reflective / Solar Control	
	Impala	87-98 / 01-02	Heat Reflective	
	Lumina Van	All	Solar Ray / Solar Control	Top left or right corner of windshield
	Venture	97-07	Solar Control	Top left or right corner of windshield
Chrysler				
	Concord	01-02	Metallized Windshield	
<u>Dodge</u>				
	Caravan	84	Metallized Windshield	
	Shadow	94	Metallized Windshield	
<u>Ford</u>				
	Crown Victoria	87-2006	Insta-Clear	
<u>Jaguar</u>				
	VDP	94-98	Heated	
	XJS	94	Heated	
	XJ6	95-98	Heated	
	XJ12	94	Heated	
Jeep				
	Liberty	95-2007		Centered 1" above the dashboard
	Wrangler	95-2007		Centered 1" above the dashboard
Land Roy				
	Country LWB		Metal Oxide	
	Discovery	01-02		
	Freelander	02		
	Range Rover	97-02	Heated	
Lincoln	.			
	Continental	87-94 / 01-02	Insta-Clear / Metallized Windshield	
	Town Car	94-97 / 01-02	Insta-Clear / Heated	
	,	2.2., 0. 02		

Make	Model	Year(s)	Feature	Alternative Placement
Mazda				
	MPV	89-98	Solar Control	Try standard mounting; may need LPT
	626	90-97	Solar Control / Metal Oxide	Try standard mounting; may need LPT
	929	90-97	Solar Control / Metal Oxide	
<u>Mercedes</u>				
	All Models	98-01		Centered below rearview mirror. Half of the transponder should be in the tinting and the other half out
Mercury				
	Grand Marquis	86-94 / 01-02	Insta-Clear / Metallized Windshield	
	Sable Villager Van	86-94 / 01-02 97-98 / 01-02	Insta-Clear / Heated Solar Control	Try standard mounting; may need LPT
Oldsmob	J	27 20, 0. 02		
Olusillob	Custom Cruiser	90-97	Solar Control	
	Station Wagon	90-97	Solal Collifor	
	Silhouette	All	Metallized Windshield	Top left corner of windshield
Plymouth				
	Neon Highliner	97-98	Heated	
	Voyager		Metallized Windshield	
<u>Pontiac</u>				
	Aztek	00-06		Top right corner of windshield
	Grand Am	96 / 00-02	Metallized Windshield	
	Grand Prix	00-02		
	Montana	99-02		Top right corner of windshield
	Transport	All		Top right corner of windshield
<u>Volkswa</u>				
	Passat	95	Metallized Windshield	

